

HOLES WERE CAUSED BY TIE DOWN STRAP HARDWARE. HOLES LOCATED ON OPPOSITE END FROM HUMIDITY INDICATOR 30 INCHES FROM BOTTOM 7 INCHES FROM FRONT. PENETRATION APPROX 1 INCH, NO APPARENT DAMAGE TO CONFIG.

-0-0-0-1--

EXCLUDED FROM AUTO-MATIC DOWNSEADING AND DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED, CONTRACT